

PIACS® MK2


PRODUCT DISCONTINUED NOTICE

NOTICE:


From December 31, 2017 FLSmidth will be discontinuing the PIACS® MK2 controller, including repair and supply of spares of the products described below.

After more than 30 years supporting the PIACS® MK2, the discontinuation is due to end-of-life status.


Why is the PIACS® MK2 no longer available?
Some key components of the MK2 system are no longer available to our supplier. It is therefore not possible to repair or replace components of the controller.



The PIACS® MK2 controller



Timeline of PIACS® controller family



Discontinued components

REPLACEMENT PRODUCT:

FLSmidth has developed the PIACS® DC4, which is the newest generation of automatic control of ESPs DC high voltage, rapping, heating and purge air.

Key benefits of the new PIACS® DC4:


- Touch panel
- Improved ESP performance
- Unique service facilities
- Flexible modular architecture
- Robust components
- Adaptable to existing installations
- Built-in ESP Manager

By upgrading to the new PIACS® DC4, you ensure a secured stability for your plant ESP equipment for the next many years.




PIACS® DC4 REPLACEMENT SOLUTION FOR MK2

EXISTING PANEL WITH PIACS MK2



PIACS DC4 BUILT-IN EXISTING PANEL



OPTIONS:

- Retrofit kit built-in the existing control panels: Limited investment and short delivery time.
- New control panels: New electrical equipment and panel pretested, certified from workshop and reduced installation time. Keep the transformer-rectifier sets.
- New back panels: New electrical equipment keeping the existing panels.

Project Centre Denmark
 FLsmidth A/S
 Vigerslev Allé 77
 DK-2500 Valby
 Copenhagen
 Tel: +45 3618 1000
 Fax: +45 3630 1820
 E-mail: info@flsmidth.com



www.flsmidthairtech.com